



Maximum Rate by Speed (Total)



Maximum Rate by Speed (Total)					
Urea (50 lb/ft ³)		Cereal Rye (45 lb/ft ³)		Turnip (39 lb/ft ³)	
Speed	Max. Rate	Speed	Max. Rate	Speed	Max. Rate
12.0	72.0	12.0	65.0	12.0	56.0
10.0	85.0	10.0	78.0	10.0	68.0
8.0	110.0	8.0	98.0	8.0	86.0
6.0	150.0	6.0	134.0	6.0	116.0
4.0	220.0	4.0	200.0	4.0	176.0

Minimum Rate by Speed (Total)					
Urea (50 lb/ft ³)		Cereal Rye (45 lb/ft ³)		Turnip (39 lb/ft ³)	
Speed	Min. Rate	Speed	Min. Rate	Speed	Min. Rate
4.0	40.0	4.0	36.0	4.0	32.0
6.0	27.0	6.0	24.5	6.0	22.0
8.0	20.0	8.0	18.0	8.0	16.0
10.0	16.0	10.0	14.0	10.0	12.0
12.0	14.0	12.0	12.0	12.0	10.0

Minimum Rate by Speed (Total)



MONTAG MANUFACTURING

3816 461st Avenue, Emmetsburg, IA 50536

(712) 852-4572 | info@montagmfg.com | <http://www.montagmfg.com>